

Appendix H

Conditions of Approval for Specified Wells

Appendix H Conditions of Approval for Specified Wells

Definition of Terms: NSO, TL, and CSU are used to make the nature of the condition of approval (COA) readily apparent. No new lease stipulations are being proposed.

No Surface Occupancy (NSO): Use or occupancy of the land surface for fluid mineral exploration or development is prohibited to protect identified resource values.

Timing Limitation (TL) (Seasonal Restriction): Prohibits surface use during specified time periods to protect identified resource values. This stipulation does not apply to the operation and maintenance of production facilities unless the findings of analysis demonstrate the continued need for such mitigation and that less stringent, project specific mitigation measures would be insufficient.

Controlled Surface Use (CSU): Use and occupancy is allowed (unless restricted by another stipulation), but identified resource values require special operational constraints that may modify the lease rights. CSU is used for operating guidance, not as a substitute for NSO or Timing Stipulation.

Pork S Fed 21-18-41-70:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Swainson's Hawk nests.

Pork S Fed 12-1-41-71:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork S Fed 14-18-41-70:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork S Fed 23-1-41-71:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork S Fed 14-1-41-71:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork S Fed 12-3-41-71:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

Pork S Fed 34-3-41-71:

TL, surface use is prohibited from March 15 through July 31 within .25 miles (line of sight) of a Mountain Plover nests or nest aggregation areas.

Pork S Fed 23-3-41-71:

TL, surface use is prohibited from March 15 through July 31 within .25 miles (line of sight) of a Mountain Plover nests or nest aggregation areas.

Pork S Fed 14-3-41-71:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

TL, surface use is prohibited from March 15 through July 31 within .25 miles of the burrowing owl nest.

Pork S Fed 43-3-41-71:

TL, surface use is prohibited from March 15 through July 31 within .25 miles (line of sight) of a Mountain Plover nests or nest aggregation areas.

Pork S Fed 21-3-41-71:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

Pork S Fed 12-12-41-71:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork S Fed 32-12-41-71:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork S Fed 14-12-41-71:

TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Golden Eagle nests.

Pipeline route between 14-12-41-71 and 21-13-41-71 will need water bars on slopes to prevent erosion and water from running down the pipeline.

Pork S Fed 23-12-41-71:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork S Fed 41-12-41-71:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork S Fed 12-13-41-71:

TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Golden Eagle nests.

TL, (Utility corridor between 12-13 and 21-13-41-71) surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Golden Eagle nests.

Pork S Fed 21-13-41-71:

Pipeline route between 14-12-41-71 and 21-13-41-71 will need water bars on slopes to prevent erosion and water from running down the pipeline.

Pork S Fed 34-13-41-71:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork S Fed 32-13-41-71:

TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Red-tailed Hawk nests.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NE Fed 43-8-42-70:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NE Fed 14-8-42-70:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NE Fed 23-8-42-70:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NE Fed 34-8-42-70:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NE Fed 12-15-42-70:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Swainson's Hawk nests.

TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Burrowing Owl nests.

Pork NE Fed 23-15-42-70:

TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Burrowing Owl nests.

Pork NE Fed 14-15-42-70:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Swainson's Hawk nests.

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

Pork NE Fed 32-17-42-70:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NE Fed 43-17-42-70:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NE Fed 41-17-42-70:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NE Fed 21-17-42-70:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NE Fed 43-19-42-70:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Swainson's Hawk nests.

Pork NE Fed 34-19-42-70:

TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Red-tailed Hawk nests.

Pork NE Fed 41-19-42-70:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Swainson's Hawk nests.

Pork NE Fed 43-20-42-70:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

Pork NE Fed 34-20-42-70:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Swainson's Hawk nests.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NE Fed 44-20-42-70:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Swainson's Hawk nests.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NE Fed 24-20-42-70:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Swainson's Hawk nests.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NE Fed 41-21-42-70:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

Pork NE Fed 21-21-42-70:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

Pork NE Fed 12-21-42-70:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

Pork NE Fed 24-21-42-70:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

Pork NE Fed 23-21-42-70:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

Pork NE Fed 14-21-42-70:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

Pork NE Fed 21-22-42-70:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NE Fed 12-22-42-70:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NE Fed 31-29-42-70:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Swainson's Hawk nests.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NE Fed 12-29-42-70:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Swainson's Hawk nests.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NE Fed 11-29-42-70:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Swainson's Hawk nests.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NE Fed 21-29-42-70:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Swainson's Hawk nests.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NE Fed 44-29-42-70:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Swainson's Hawk nests.

Pork NE Fed 42-29-42-70:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Swainson's Hawk nests.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NE Fed 41-29-42-70:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Swainson's Hawk nests.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NE Fed 43-29-42-70:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Swainson's Hawk nests.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NE Fed 34-29-42-70:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Swainson's Hawk nests.

TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Golden Eagle nests.

Pork NE Fed 22-29-42-70:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Swainson's Hawk nests.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NE Fed 33-29-42-70:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Swainson's Hawk nests.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NE Fed 24-29-42-70:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

Pork NE Fed 31-30-42-70:

TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Red-tailed Hawk nests.

Pork NE Fed 32-30-42-70:

TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Red-tailed Hawk nests.

Pork NE Fed 31-33-42-70:

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

Pork NW Fed 32-12-42-71:

TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Red-tailed Hawk nests.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Swainson's Hawk nests.

Pork NW Fed 41-12-42-71:

TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Red-tailed Hawk nests.

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Swainson's Hawk nests.

Pork NW Fed 32-13-42-71:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NW Fed 12-13-42-71:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NW Fed 23-13-42-71:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NW Fed 32-22-42-71:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Golden Eagle nests.

Limit brush mowing to no more that 50' from the wellhead.

Pork NW Fed 43-22-42-71:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Golden Eagle nests.

Pork NW Fed 34-22-42-71:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Golden Eagle nests.

Pork NW Fed 44-22-42-71:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Golden Eagle nests.

Pork NW Fed 34-24-42-71:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NW Fed 44-24-42-71:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Red-tailed Hawk nests.

Pork NW Fed 43-24-42-71:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Pork NW Fed 41-25-42-71:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Red-tailed Hawk nests.

Pork NW Fed 42-25-42-71:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Red-tailed Hawk nests.

Pork NW Fed 21-27-42-71:

TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Golden Eagle nests.

Pork NW Fed 43-27-42-71:

TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Burrowing Owl nests.

Pork NW Fed 41-27-42-71:

TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Burrowing Owl nests.

Pork NW Fed 32-27-42-71:

TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Burrowing Owl nests.

Pork NW Fed 42-35-42-71:

TL, surface use is prohibited from March 15 through July 31 within .25 miles (line of sight) of a Mountain Plover nests or nest aggregation areas.

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

Pork NW Fed 31-35-42-71:

TL, surface use is prohibited from March 15 through July 31 within .25 miles (line of sight) of a Mountain Plover nests or nest aggregation areas.

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

Pork NW Fed 32-35-42-71:

TL, surface use is prohibited from March 15 through July 31 within .25 miles (line of sight) of a Mountain Plover nests or nest aggregation areas.

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

Pork NW Fed 21-35-42-71:

TL, surface use is prohibited from March 15 through July 31 within .25 miles (line of sight) of a Mountain Plover nests or nest aggregation areas.

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

Pork NW Fed 11-35-42-71:

TL, surface use is prohibited from March 15 through July 31 within .25 miles (line of sight) of a Mountain Plover nests or nest aggregation areas.

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.

JWS Fed 34-35-42-71:

TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Red-tailed Hawk nests.

JWS Fed 44-35-42-71:

TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Red-tailed Hawk nests.

JWS Fed 43-35-42-71:

TL, surface use is prohibited from March 15 through July 31 within .25 miles (line of sight) of a Mountain Plover nests or nest aggregation areas.

TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at

Well location will not be approved: Wildlife issues

Pork NE Fed 32-29-42-70:

NSO, No surface occupancy is allowed within 0.25 mile (line-of-sight) of Ferruginous Hawk nests.

NSO, No surface occupancy is allowed within 0.25 mile (line-of-sight) of Ferruginous Hawk nests.

Pork NW Fed 32-25-42-71:

NSO, No surface occupancy is allowed within 0.25 mile (line-of-sight) of Ferruginous Hawk nests.

Pork NW Fed 31-25-42-71:

NSO, No surface occupancy is allowed within 0.25 mile (line-of-sight) of Ferruginous Hawk nests.

Conditions of Approval for Compressor Sites

Compressor 12-41-71 SWSW:

- TL, surface use is prohibited from February 1 through July 31 within 0.50 miles (line of sight) of Golden Eagle nests.

Compressor 17-42-70 NWSE:

- TL, surface use is prohibited from March 1 through July 31 within 0.50 miles (line of sight) of Ferruginous Hawk nests.

Compressor 29-42-70 SWNW:

- TL, surface use is prohibited from March 1 through June 15 within two miles (line of sight) of a Sage Grouse display ground, and noise from production facilities must not exceed 49 decibels (10 dBA above background noise) at the display ground.